

Truflex transfers

Truflex (Standardversion)

Truflex ist stark genug für (industrielle) Firmenkleidung, aber auch weich und flexibel für Kleidung wie Polos, T-Shirts, Pullover und sogar Babykleidung. Die Übertragung garantiert scharfe Bilder und ist beständig gegenüber den anspruchsvollsten Waschprogrammen. Truflex erfüllt die Öko-Tex-Zertifizierung Klasse 1. Nach der Versiegelung fühlt sich das Truflex-Transfer fast so an, als wäre es ein Teil des Textils. Ein sehr vielseitiges Transfer mit endlosen Möglichkeiten. Industrielle Wäsche bei 95 °C ist möglich.

Truflex Industrial

Wenn es hart auf hart kommt, machen sich die Harten auf den Weg! Für Situationen, in denen höchste Anforderungen an Textilien und Transfer gestellt werden, ist Truflex Industrial der Inbegriff. Dieses Emblem hält nicht nur intensivsten Industriewaschen stand, sondern ist auch mit dem Öko-Tex Standard 100-Zertifikat der Produktklasse II ausgezeichnet. Trotz der hohen Waschtemperatur bleibt dieser Transfer klar und farbecht.

Truflex FR (flammhemmend)

Truflex FR ist auch mit einem anderen Kleber und angepasstem Produktionsverfahren erhältlich. Diese von Thermopatch entwickelte flammhemmende (FR) Version wurde unabhängig getestet. Im Abschnitt „Zertifikate“ auf dieser Seite finden Sie Testberichte mit mehr als zehn verschiedenen Textilarten. Zusätzlich zu den flammhemmenden Eigenschaften der FR-Version entsprechen andere Spezifikationen denen des Standard-Truflex-Transfers. Die FR-Version von Truflex kann bis zu 60 °C gewaschen werden.

Truflex-Transfers können sehr detaillierte Bilder enthalten und können in fast jeder PMS-Farbe gedruckt werden. Auch gut sichtbare Farben sind möglich, in Orange, Grün, Rot, Pink und Gelb. Die Transfers verfügen über einen Hot-Peel-Träger, der leicht entfernt werden kann.

Truflex, Truflex Industrial und Truflex FR haben eine Mindestbestellmenge von 25 Stück in jeder gewünschten Größe.

Truflex

Truflex	12-15 seconds	Hot Peel	185-160 + °C	Pressure 0.5 kg / cm ²	95
---------	---------------	----------	-----------------	--------------------------------------	----



Truflex transfers are compliant to Oekotex 100 Class 1, under certificate number 1110043 Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Suitable for all textiles which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical and drying resistance.

Limitations of use

None, when washing instructions of the underlying textile are followed.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Truflex Industrial

Truflex Industrial	14 seconds	Hot Peel	204 + °C	Pressure 0.5 kg / cm ²	95
-----------------------	------------	----------	-------------	--------------------------------------	----



Truflex Industrial transfers are compliant to Oekotex 100 Class 2, under certificate number 2311267 Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Developed for severe laundry processing of heavy workwear and white workwear textiles, which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical and drying resistance.

Limitations of use

This products warrants high temperature heat sealing for an optimal performance in laundry processing. Please make sure the textile can withstand the required heat sealing temperatures.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Truflex FR



Truflex FR transfers have been found compliant to EN ISO 11611 and EN ISO 11612 on several FR workwear textiles as tested by Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Suitable for all textiles which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical resistance.

Limitations of use

None, when washing instructions of the underlying textile are followed.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed. Please note: good bonding can be prevented in pre-conditioned fabrics with a dirt or water repellant coatings.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Scroll down for Truflex FR and Truflex Industrial.

Truflex Transfers (up to 95 °C laundry wash)			
Type of Fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	145	12	4-5 (Medium/High)
Polyurethane or PVC Coated Polyester (Rainwear) Cover with baking paper.	135 - 150	15	2-3 (Low)
Knitted Fabrics 100% Polyester Viscose Acrylic (Sportswear, Light Workwear)	Preheat 145 - 155	7-10 15	4-5 (Medium/High)
Knitted Fabrics 100% Wool Cotton (Sportswear, Light Workwear)	145 - 165 Repress	15 7-10	4-5 (Medium/High)
Knitted Fabrics Cotton or Polyester with Elastane 98%/2%	Preheat 145 - 155	10 15	2-3 (Low)

Cotton or Polyester Cotton 65%/35%	160	15	4-5 (Medium/High)
Flame-Retardant Cotton or Polyester Cotton (FR Treated Proban®)	Preheat 160	7-10 15	4-5 (Medium/High)
Cotton/Polyamide 55%/45%	160	15	4-5 (Medium/High)
Cotton/Polyester 65%/35% or 60%/40% (with DWR Finish)*	165	15	4-5 (Medium/High)
Aramide/Viscose 50%/50%	155	15	4-5 (Medium/High)
Linen, 100%	165	15	4-5 (Medium/High)
Aramide (Nomex III), 100%	155	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish)*	Preheat 160	7-10 15	4-5 (Medium/High)
Polyester 100% (with DWR finish)*	Preheat 160	7-10 15	4-5 (Medium/High)
Polyester Cleanroom material anti-static 99%/1%	Preheat 165	7-10 18	4-5 (Medium/High)

Truflex FR Transfers (up to 60 °C laundry wash)			
Type of fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	145	12	4-5 (Medium/High)
Polyurethane or PVC coated polyester (FR rainwear), cover with baking paper	135 - 150	15	2-3 (Low)
Knitted fabrics 100% polyester (Sportswear, light workwear FR)	Preheat 145 - 155	7-10 15	4-5 (Medium/High)
Knitted fabrics 100% cotton (Sportswear, light workwear FR)	145 - 165 Repress	15 7-10	4-5 (Medium/High)
Knitted fabrics cotton or polyester with elastane 98%/2% (FR)	Preheat 145 - 155	10 15	2-3 (Low)
Cotton or polyester cotton (FR) 65%/35%	160	15	4-5 (Medium/High)
Flame retardant cotton or polyester cotton (FR treated Proban®)	Preheat 160	7-10 15	4-5 (Medium/High)
Cotton/polyamide 55%/45% (FR treated Proban®)	160	15	4-5 (Medium/High)
Cotton/polyester 65%/35% or 60%/40% (with DWR finish and FR)*	165	15	4-5 (Medium/High)
Aramide/Viscose 50%/50%	155	15	4-5 (Medium/High)
Aramide (Nomex III), 100%	155	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish and FR)*	Preheat 160	7-10 15	4-5 (Medium/High)

Truflex Industrial Transfers (up to 95 °C laundry wash)			
Type of fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	-	-	-
Polyurethane or PVC coated polyester (rainwear, FR), cover with baking paper	-	-	-
Knitted fabrics, 100% polyester (Sportswear, light workwear, FR)	-	-	-
Knitted fabrics, 100% Cotton (Sportswear, light workwear, FR)	195 – 204	15	4-5 (Medium/High)
Knitted fabrics, cotton or polyester with elastane 98%/2% (FR)	-	-	-
Cotton or polyester cotton (FR) 65%/35%	195 – 204	15	4-5 (Medium/High)
Flame retardant cotton or polyester cotton (FR treated, Proban®)	Preheat 195 – 204	7-10 15	4-5 (Medium/High)
Cotton/polyamide 55%/45% (FR treated, Proban®)	195 – 204	15	4-5 (Medium/High)
Cotton/polyester 65%/35% or 60%/40% (with DWR finish and FR)	195 – 204	15	4-5 (Medium/High)
Aramid/Viscose 50%/50%	195 – 204	15	4-5 (Medium/High)
Aramid (Nomex III), 100%	195 – 204	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish and FR)*	-	-	-

**DWR finish: Durable Water Repellent finish, meaning a water (dirt, oil) repellent coating on textiles based on silicone, nanotechnology, wax, and fluorocarbon.*

FR: Flame Retardant

Disclaimer

No rights can be derived from the instructions or data provided online. The information is intended for general guidance only and is subject to change without notice. We do not guarantee the accuracy, completeness, or reliability of the information provided. Users are advised to verify any information before acting on it. We accept no liability for any damage incurred because of relying on this information.