

Transfer Truflex

Truflex (versión estándar)

Truflex es resistente para ropa corporativa (industrial), pero también suave y flexible para prendas como polos, camisetas, suéteres e incluso ropa de bebé. El transfer garantiza imágenes nítidas y es resistente a los programas de lavado más exigentes. Truflex cumple con la certificación Oeko-Tex clase 1. Después del sellado, el transfer Truflex se siente casi como parte del tejido. Es un transfer muy versátil con infinitas posibilidades. Soporta lavado industrial a 95 °C.

Truflex Industrial

¡Cuando las cosas se ponen exigentes, nos exigimos poner en marcha! Para aquellas situaciones en las que se exige lo máximo tanto del textil como del transfer, Truflex Industrial es el epítome. Este emblema no sólo resiste los lavados industriales más intensivos sino que también ha recibido el certificado Oeko-Tex Standard 100 clase de producto II. A pesar de la alta temperatura de lavado, este transfer sigue siendo nítido y mantiene el color.

Truflex FR (Piroretardante)

Truflex FR también está disponible con un adhesivo diferente y un proceso de producción adaptado. Esta versión piroretardante (FR), desarrollada por Thermopatch, ha sido probada de forma independiente. Consulte la sección «Certificados» en esta página para obtener informes de pruebas con más de diez tipos diferentes de textiles. Además de las cualidades retardantes a la llama de la versión FR, cumple las mismas especificaciones que las del transfer Truflex estándar. La versión FR de Truflex se puede lavar hasta 60 °C.

Los transfers Truflex pueden contener imágenes muy detalladas y pueden imprimirse en casi cualquier color PMS. Además, son posibles colores de alta visibilidad, naranja, verde, rojo, rosa y amarillo. Los transfers cuentan con un soporte que se quita en caliente y fácilmente.

Truflex, Truflex Industrial y Truflex FR tienen un pedido mínimo de 25 unidades en cualquier tamaño deseado.

Truflex

Truflex					
---------	---	---	---	---	---



Truflex transfers are compliant to Oekotex 100 Class 1, under certificate number 1110043 Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Suitable for all textiles which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical and drying resistance.

Limitations of use

None, when washing instructions of the underlying textile are followed.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Truflex Industrial

Truflex Industrial					
---------------------------	---	---	---	---	---



Truflex Industrial transfers are compliant to Oekotex 100 Class 2, under certificate number 2311267 Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Developed for severe laundry processing of heavy workwear and white workwear textiles, which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical and drying resistance.

Limitations of use

This products warrants high temperature heat sealing for an optimal performance in laundry processing. Please make sure the textile can withstand the required heat sealing temperatures.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Truflex FR



Truflex FR transfers have been found compliant to EN ISO 11611 and EN ISO 11612 on several FR workwear textiles as tested by Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Suitable for all textiles which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical resistance.

Limitations of use

None, when washing instructions of the underlying textile are followed.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed. Please note: good bonding can be prevented in pre-conditioned fabrics with a dirt or water repellant coatings.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Scroll down for Truflex FR and Truflex Industrial.

Truflex Transfers (up to 95 °C laundry wash)			
Type of Fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	145	12	4-5 (Medium/High)
Polyurethane or PVC Coated Polyester (Rainwear) Cover with baking paper.	135 - 150	15	2-3 (Low)
Knitted Fabrics 100% Polyester Viscose Acrylic (Sportswear, Light Workwear)	Preheat 145 - 155	7-10 15	4-5 (Medium/High)
Knitted Fabrics 100% Wool Cotton (Sportswear, Light Workwear)	145 - 165 Repress	15 7-10	4-5 (Medium/High)
Knitted Fabrics Cotton or Polyester with Elastane 98%/2%	Preheat 145 - 155	10 15	2-3 (Low)

Cotton or Polyester Cotton 65%/35%	160	15	4-5 (Medium/High)
Flame-Retardant Cotton or Polyester Cotton (FR Treated Proban®)	Preheat 160	7-10 15	4-5 (Medium/High)
Cotton/Polyamide 55%/45%	160	15	4-5 (Medium/High)
Cotton/Polyester 65%/35% or 60%/40% (with DWR Finish)*	165	15	4-5 (Medium/High)
Aramide/Viscose 50%/50%	155	15	4-5 (Medium/High)
Linen, 100%	165	15	4-5 (Medium/High)
Aramide (Nomex III), 100%	155	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish)*	Preheat 160	7-10 15	4-5 (Medium/High)
Polyester 100% (with DWR finish)*	Preheat 160	7-10 15	4-5 (Medium/High)
Polyester Cleanroom material anti-static 99%/1%	Preheat 165	7-10 18	4-5 (Medium/High)

Truflex FR Transfers (up to 60 °C laundry wash)			
Type of fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	145	12	4-5 (Medium/High)
Polyurethane or PVC coated polyester (FR rainwear), cover with baking paper	135 - 150	15	2-3 (Low)
Knitted fabrics 100% polyester (Sportswear, light workwear FR)	Preheat 145 - 155	7-10 15	4-5 (Medium/High)
Knitted fabrics 100% cotton (Sportswear, light workwear FR)	145 - 165 Repress	15 7-10	4-5 (Medium/High)
Knitted fabrics cotton or polyester with elastane 98%/2% (FR)	Preheat 145 - 155	10 15	2-3 (Low)
Cotton or polyester cotton (FR) 65%/35%	160	15	4-5 (Medium/High)
Flame retardant cotton or polyester cotton (FR treated Proban®)	Preheat 160	7-10 15	4-5 (Medium/High)
Cotton/polyamide 55%/45% (FR treated Proban®)	160	15	4-5 (Medium/High)
Cotton/polyester 65%/35% or 60%/40% (with DWR finish and FR)*	165	15	4-5 (Medium/High)
Aramide/Viscose 50%/50%	155	15	4-5 (Medium/High)
Aramide (Nomex III), 100%	155	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish and FR)*	Preheat 160	7-10 15	4-5 (Medium/High)

Truflex Industrial Transfers (up to 95 °C laundry wash)			
Type of fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	-	-	-
Polyurethane or PVC coated polyester (rainwear, FR), cover with baking paper	-	-	-
Knitted fabrics, 100% polyester (Sportswear, light workwear, FR)	-	-	-
Knitted fabrics, 100% Cotton (Sportswear, light workwear, FR)	195 – 204	15	4-5 (Medium/High)
Knitted fabrics, cotton or polyester with elastane 98%/2% (FR)	-	-	-
Cotton or polyester cotton (FR) 65%/35%	195 – 204	15	4-5 (Medium/High)
Flame retardant cotton or polyester cotton (FR treated, Proban®)	Preheat 195 – 204	7-10 15	4-5 (Medium/High)
Cotton/polyamide 55%/45% (FR treated, Proban®)	195 – 204	15	4-5 (Medium/High)
Cotton/polyester 65%/35% or 60%/40% (with DWR finish and FR)	195 – 204	15	4-5 (Medium/High)
Aramid/Viscose 50%/50%	195 – 204	15	4-5 (Medium/High)
Aramid (Nomex III), 100%	195 – 204	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish and FR)*	-	-	-

**DWR finish: Durable Water Repellent finish, meaning a water (dirt, oil) repellent coating on textiles based on silicone, nanotechnology, wax, and fluorocarbon.*

FR: Flame Retardant

Disclaimer

No rights can be derived from the instructions or data provided online. The information is intended for general guidance only and is subject to change without notice. We do not guarantee the accuracy, completeness, or reliability of the information provided. Users are advised to verify any information before acting on it. We accept no liability for any damage incurred because of relying on this information.