

Transferts Truflex

Truflex (version standard)

Le Truflex est suffisamment résistant pour les vêtements de travail (industrie), mais également souple et flexible pour des vêtements tels que polos, T-shirts, mais tout autant pour les vêtements de bébé. Le transfert présente des images nettes et résiste à la plupart des programmes de lavages demandés. Le Truflex répond aux exigences de la certification Oeko-Tex Classe 1. Après thermofixation, le Truflex fait partie intégrante du textile. Un transfert très polyvalent avec des possibilités infinies. Le lavage industriel à 95 °C est possible.

Truflex Industriel

Quand les exigences en matière de résistance au traitement industriel augmentent, il faut choisir le Truflex industriel qui est la quintessence. Il n'est pas seulement résistant aux lavages industriels les plus intensifs mais il a également reçu la certification Oeko-Tex Standard 100 classe II. Après de nombreux lavages à haute température, ce transfert reste net et très coloré.

Truflex FR (retardant flamme)

Le Truflex est également disponible avec une colle différente et un procédé de production adapté. Il s'agit de la version ignifuge, développée par Thermopatch, qui a été testée par un centre indépendant. Consultez la section 'Certificats' sur cette page pour les rapports de tests sur plus de 10 qualités de textile différentes. En plus de cette propriété ignifuge de la version FR, il dispose des mêmes spécificités que le Truflex standard. La version FR est résistante au lavable jusqu'à 60 °C.

Les transferts Truflex peuvent être réalisés avec un graphisme très fin et être imprimés dans la majorité des coloris PMS. Les coloris haute visibilité sont également possibles: orange, vert, rouge, rose et jaune. Les transferts sont présentés sur un support à retirer à chaud qui s'enlève facilement.

Pour les 3 versions, commande minimum de 25 pièces quel que soit le format.

Truflex



Truflex transfers are compliant to Oekotex 100 Class 1, under certificate number 1110043 Centexbel.

(See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Suitable for all textiles which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical and drying resistance.

Limitations of use

None, when washing instructions of the underlying textile are followed.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Truflex Industrial

Truflex Industrial	 14 seconds	 Hot Peel	 204 °C	 Pressure 0.5 kg / cm ²	 95
---------------------------	--	--	--	---	--



Truflex Industrial transfers are compliant to Oekotex 100 Class 2, under certificate number 2311267 Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Developed for severe laundry processing of heavy workwear and white workwear textiles, which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical and drying resistance.

Limitations of use

This products warrants high temperature heat sealing for an optimal performance in laundry processing. Please make sure the textile can withstand the required heat sealing temperatures.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Truflex FR



Truflex FR transfers have been found compliant to EN ISO 11611 and EN ISO 11612 on several FR workwear textiles as tested by Centexbel. (See: tab 'Certificates' on this page)

Application

Silk screen printed transfers which are applied to textile or other heat sealable materials by heat and pressure for decoration or identification.

Properties

Suitable for all textiles which allow the thermoplastic adhesive to penetrate and bind itself to it and which are resistant to its application temperatures. Good chemical resistance.

Limitations of use

None, when washing instructions of the underlying textile are followed.

Physical properties

Various, depending on size.

Before sealing

Ensure that the to be marked textile is free of lint, dust, dirt and no seams, zipper, buttons etc. are near the place where the heat sealing will be performed. Please note: good bonding can be prevented in pre-conditioned fabrics with a dirt or water repellant coatings.

Handling and storage

Keep away from oxidizing agents, from strongly alkaline en strongly acid materials. Store out of direct sunlight, in a cool and dry place

Shelf life: One year when stored in their original packing, out of direct sunlight, in a cool and dry place.

Scroll down for Truflex FR and Truflex Industrial.

Truflex Transfers (up to 95 °C laundry wash)			
Type of Fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	145	12	4-5 (Medium/High)
Polyurethane or PVC Coated Polyester (Rainwear) Cover with baking paper.	135 - 150	15	2-3 (Low)
Knitted Fabrics 100% Polyester Viscose Acrylic (Sportswear, Light Workwear)	Preheat 145 - 155	7-10 15	4-5 (Medium/High)
Knitted Fabrics 100% Wool Cotton (Sportswear, Light Workwear)	145 - 165 Repress	15 7-10	4-5 (Medium/High)
Knitted Fabrics Cotton or Polyester with Elastane 98%/2%	Preheat 145 - 155	10 15	2-3 (Low)

Cotton or Polyester Cotton 65%/35%	160	15	4-5 (Medium/High)
Flame-Retardant Cotton or Polyester Cotton (FR Treated Proban®)	Preheat 160	7-10 15	4-5 (Medium/High)
Cotton/Polyamide 55%/45%	160	15	4-5 (Medium/High)
Cotton/Polyester 65%/35% or 60%/40% (with DWR Finish)*	165	15	4-5 (Medium/High)
Aramide/Viscose 50%/50%	155	15	4-5 (Medium/High)
Linen, 100%	165	15	4-5 (Medium/High)
Aramide (Nomex III), 100%	155	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish)*	Preheat 160	7-10 15	4-5 (Medium/High)
Polyester 100% (with DWR finish)*	Preheat 160	7-10 15	4-5 (Medium/High)
Polyester Cleanroom material anti-static 99%/1%	Preheat 165	7-10 18	4-5 (Medium/High)

Truflex FR Transfers (up to 60 °C laundry wash)			
Type of fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	145	12	4-5 (Medium/High)
Polyurethane or PVC coated polyester (FR rainwear), cover with baking paper	135 - 150	15	2-3 (Low)
Knitted fabrics 100% polyester (Sportswear, light workwear FR)	Preheat 145 - 155	7-10 15	4-5 (Medium/High)
Knitted fabrics 100% cotton (Sportswear, light workwear FR)	145 - 165 Repress	15 7-10	4-5 (Medium/High)
Knitted fabrics cotton or polyester with elastane 98%/2% (FR)	Preheat 145 - 155	10 15	2-3 (Low)
Cotton or polyester cotton (FR) 65%/35%	160	15	4-5 (Medium/High)
Flame retardant cotton or polyester cotton (FR treated Proban®)	Preheat 160	7-10 15	4-5 (Medium/High)
Cotton/polyamide 55%/45% (FR treated Proban®)	160	15	4-5 (Medium/High)
Cotton/polyester 65%/35% or 60%/40% (with DWR finish and FR)*	165	15	4-5 (Medium/High)
Aramide/Viscose 50%/50%	155	15	4-5 (Medium/High)
Aramide (Nomex III), 100%	155	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish and FR)*	Preheat 160	7-10 15	4-5 (Medium/High)

Truflex Industrial Transfers (up to 95 °C laundry wash)			
Type of fabric	Temp. °C	Pressing time in sec.	Pressure in Bar Low/Medium/High
Fleece, 100% Polyester	-	-	-
Polyurethane or PVC coated polyester (rainwear, FR), cover with baking paper	-	-	-
Knitted fabrics, 100% polyester (Sportswear, light workwear, FR)	-	-	-
Knitted fabrics, 100% Cotton (Sportswear, light workwear, FR)	195 – 204	15	4-5 (Medium/High)
Knitted fabrics, cotton or polyester with elastane 98%/2% (FR)	-	-	-
Cotton or polyester cotton (FR) 65%/35%	195 – 204	15	4-5 (Medium/High)
Flame retardant cotton or polyester cotton (FR treated, Proban®)	Preheat 195 – 204	7-10 15	4-5 (Medium/High)
Cotton/polyamide 55%/45% (FR treated, Proban®)	195 – 204	15	4-5 (Medium/High)
Cotton/polyester 65%/35% or 60%/40% (with DWR finish and FR)	195 – 204	15	4-5 (Medium/High)
Aramid/Viscose 50%/50%	195 – 204	15	4-5 (Medium/High)
Aramid (Nomex III), 100%	195 – 204	15	4-5 (Medium/High)
Polyamide (Nylon), 100% (with DWR finish and FR)*	-	-	-

**DWR finish: Durable Water Repellent finish, meaning a water (dirt, oil) repellent coating on textiles based on silicone, nanotechnology, wax, and fluorocarbon.*

FR: Flame Retardant

Disclaimer

No rights can be derived from the instructions or data provided online. The information is intended for general guidance only and is subject to change without notice. We do not guarantee the accuracy, completeness, or reliability of the information provided. Users are advised to verify any information before acting on it. We accept no liability for any damage incurred because of relying on this information.