

Custom Coating & Laminating

Thermopatch has two ways of coating/laminating:

- Powder coating. This is mainly used for cotton or a blend of cotton with polyester
- Laminate. This process is more for special or delicate fabrics

Keep in mind that some loss of material occurs: usually about 2-3 running metres when laminating, and 8-10 running metres when powder coating. To find out if a fabric can be coated or laminated, it is advisable to make a sample and test this (at least A4 size).

After coating or laminating, the textile is processed and delivered as patches or on rolls.

	Length	Width
Powder coating	At least 10 running meters	Minimum width 130 cm, maximum 160 cm
Laminate	At least 25 linear meters	Minimum/maximum width 150cm; the net output is 142 cm